# PORTWEST. USER INFORMATION

RFF: 5USP



ANSI/ISEA 107 CERTIFIED

www.portwest.com/declarations

	A	D	
	CM	CM	
SHORT	152-164	74	
REG	164-176	79	
TALL	176-188	84	
X TALL	188-202	92	
	_		



В	INCHES	CM	EURO
XS	32"-34"	80-88	40-44
S	36"-38"	92-96	46-48
M	40"-41"	100-104	50-52
L	42"-44"	108-112	54-56
XL	46"-48"	116-124	58-62
XXL	50"-52"	128-132	64-66
3XL	54"-55"	136-140	68-70
4XL	56"-58"	144-148	72-74
5XL	60"-64"	152-160	76-80

c	INCHES	CM	DE	FR
XS	26-28	68-72	42-44	34-36
S	30-32	76-80	46-48	38-40
M	33-34	84-88	50	42-44
L	36-38	92-96	52-54	46-48
XL	40-41	100-104	56	50-52
XXL	42-44	108-112	58-60	54-56
3XL	46-47	116-120	62	58-60
4XL	48-50	124-128	64-68	62-64

## MANUFACTURER

PROFHUESI, ΠΡΟИЗВОДИТЕЛ, PROIZVOĐAČ, VÝROBCE, TOOTJA, VALMISTAJA, FABRICANT, HERSTELLER, KATAZKEYAZTHZ, GYÁRTÓ, FABBRICANTE, RAŽOTĀJS, GAMINTOJAS, ПРОИЗВОДИТЕЛ, PRODUSENT, PRODUCENT, FABRICANTE, PRODUCATOR, ПРОИЗВОДИТЕЛЬ, PROIZVOĐAČ, VÝROBCA, PROIZVAJALEC, TILLVERKARE, ÜRETICI, BUPOБНИЯ

PORTWEST, WESTPORT, CO MAYO, IRELAND

### **TEST HOUSE**

AGJENSIA ETESTIMIT, ЛАБОРАТОРИЯ ЗА ИЗПИТВАНЕ, ISPITNA KUĆA, ZKUŠEBNÍ DŮM, TESTHUIS, TEST MAJA, TESTAAJA, ORGANISME NOTIFIE, TESTIERHAUS, ΔΟΜΗ ΔΟΚΙΜΩΝ, TEST HOUSE, LABORATORIO, TESTA VIETA, TESTAVIMO ISTAIGA. TECT KYKA. TESTORGAN. LABORATORIUM BADAJĄCE, CASA DE TESTE, ИСПЫТАТЕЛЬНЫЙ ЦЕНТР, ISPITNA KUĆA, CERTIFIKAČNÝ ORGAN, TESTNA HIŠA, LABORATORIO DE ENSAYOS, TESTHUS, TEST KURULUŞU, ВИПРОБУВАЛЬНИЙ ЦЕНТР

INTERTEK The Warehouse, Brewery Lane, Leigh, WN7 2RJ UK

Notified body number: 0362

SATRA Wyndham Way, Telford Way, Kettering, Northamptonshire,

NN16 8SD. United Kingdom Notified body number: 0321

Bracetown Business Park, Clonee, Dublin 15, D15 YN2P Ireland

Notified Body: 2777

Vartest Laboratories, Inc., 19 West 36th Street,

10th Floor New York, NY 10018, ISO/IEC 17025 Testing Certificate No.

through A2LA is 2180.01

Plaza Emilio Sala 1, 03801 Alcov, Alicante, Spain

Notified body number: 0161

Institut fur Okologie, Technik und Innovation GmbH, Spengergasse

20 1050 Vienna, Austria Notified body number: 0534

Please read these instructions carefully before using this safety clothing. You should also consult your safety officer or immediate superior with regard to suitable garments for your specific work situation. Store these instructions carefully so that you can consult them at any time.



Refer to the garment label for detailed information on the corresponding standards. Only standards and icons that appear on both the garment and the user information below are applicable.



ANSI/ISEA 107-2015

American National Standard for High Visibility Safety Apparel and Accessories

Classifications (ANSI/ISEA 107-2015)

X - Type of garment suited for work environment

Y - Class for the flourescent and reflective surface

Type 0 Off-Road and Non-Roadway Use

Type R: Roadway and Temporary Traffic Control Zones

Type P: Emergency, Incident Responders, Law Enforcement Personnel

Class 1 Minimum level (Type 0 only) Class 2 Intermediate level (Type R and P) Class 3 Highest level (Type R and P) Class E Supplemental Item



Indicates Flame Resistance 'FR' or 'Not FR'. This garment is not flame resistant as defined by ANSI/ISEA 107-2015 Section 10.5.

Limitations of use (EN ISO 20471:2013 + A1:2016, RIS 3279 & ANSI/ISEA 107-2015): Always wear the garment fastened. Keep clean: Should the High Visibility properties of this garment become irrecoverably soiled or contaminated, replace with a new one. This garment is suitable for wear during an entire working day and contains no toxic substances that can affect health adversely in any other way. No allergic reactions due to skin contact with this garment are known. Do not attempt to repair damaged garments, All garments should be discarded safely. The clothing should not be altered or fitted with extra labels or logos. The clothing should only be worn in situations for which it is intended.

Limitations of use (ANSI/ISEA 107-2015): For FR garments please refer to the FR user information

sheet. Please Refer to Appendix F for U.S. Federal Highway Administration recommendations for additional information. Class Enarments are intended to be worn with Class 2 or 3. garments. When done so, Class 3 protection is given.

Available Size & Selection: Fit according to correct chest and waist size, refer to size chart. These garments have built in allowance for comfort and to allow the garment to be worn over medium bulky clothing.

Storage: DO NOT store in places subject to direct or strong sunlight. Store in clean, dry conditions.

After-care: After care (ANSI/ISEA 107 2015):Garments have a limited lifetime that will vary depending on the item and use, garments should be periodically evaluated to ensure performance level to ANSI/ISEA 107 2015. As a guide, garments that are worn daily should be checked every 3 months or after no more than 25 washes. Garments that are worn less than daily should be checked every year or after no more than 25 washes. Garments should be compared to a new garment to ensure its continuing suitability. Additionally, inspect garments for damage to fabric or tape, excessive soiling or abrasion hefore each use

Fibre Content Label: Refer to garment label for corresponding content details.

Warning: Where there is a hood, peripheral vision and hearing may be impaired.

Retroreflective tape and labels: Retroreflective tape or labels should not be ironed! Please refer to the garment label for the number and wash cycles claimed. The stated maximum number of cleaning cycles is not the only factor related to the lifetime of the garment. The lifetime will also depend on usage, care storage, etc. Garments should be discarded when the protective qualities no longer apply eq, 1. Maximum number of washes is reached. 2. The material has been damaged either by fading or has been torn. 3. The reflective qualities of the tape have faded. 4. Garment is permanently soiled, cracked, burned or heavily abraded.

Wash Care Labels: Refer to garment label for corresponding washing details.

30	Max temp 30°C, permanent press		Line dry/hang to dry	MAX	Maximum
(40 <u>)</u>	Max temp 40°C, permanent press	Ш	Drip dry	<b>50</b> x	50 Washes
40	Max temp 40°C, normal	$\bowtie$	Do not iron	MAX <b>25</b> x	Maximum 25 Washes
m	Max temp 60°C, normal	$\overline{\Box}$	Iron Low	MAX	Maximum
<u>~</u>	Do Not Bleach	<u></u>	Iron Medium	<b>12</b> x	12 Washes
		Ø	Do not dry clean	MAX	Maximum
	Do not tumble dry	(P)	Dry clean - Any solvent	<b>5</b> x	5 Washes

except Trichloroethylene

Tumble dry low

Tumble dry medium

www.portwest.com/declarations

VARTEST

AITEX